


说明:
 - 带锻造的锉柄，毫无缺陷的钢结构
 - 均匀的锉纹和锉齿

应用:
 车间和工厂用优质锉刀



Hieb 1 grob Hieb 2 mittel Hieb 3 fein



- 400100 扁锉 锉纹 1 (粗)
- 400200 扁锉 锉纹 2 (中)
- 400300 扁锉 锉纹 2 (中)

锉纹长度 mm	400100 (RG 4070)	400200 (RG 4070)	400300 (RG 4070)	横截面 mm
100	●	●	●	12×2,5
150	●	●	●	16×4
200	●	●	●	20×5
250	●	●	●	25×6
300	●	●	●	30×6,5
350	●	●	—	35×7,5



- 401100 方锉 锉纹 1 (粗)
- 401200 方锉 锉纹 2 (中)
- 401300 方锉 锉纹 3 (细)

锉纹长度 mm	401100 (RG 4070)	401200 (RG 4070)	401300 (RG 4070)	横截面 mm
100	●	●	●	4
150	●	●	●	6
200	●	●	●	8
250	●	●	●	10
300	●	●	—	12



- 402100 三角锉 锉纹1 (粗)
- 402200 三角锉 锉纹2 (中)
- 402300 三角锉 锉纹3 (细)

锉纹长度 mm	402100 (RG 4070)	402200 (RG 4070)	402300 (RG 4070)	横截面 mm
100	●	●	●	8,0
150	●	●	●	11,0
200	●	●	●	15,0
250	●	●	●	17,5
300	●	●	—	20,0



- 403100 半圆锉 锉纹 1 (粗)
- 403200 半圆锉 锉纹 2 (中)
- 403300 半圆锉 锉纹 3 (细)

锉纹长度 mm	403100 (RG 4070)	403200 (RG 4070)	403300 (RG 4070)	横截面 mm
150	●	●	●	16×4,5
200	●	●	●	20×6
250	●	●	●	25×7
300	●	●	●	30×8,5
350	●	—	—	35×10

● = 德国中央仓库库存
 ○ = 德国工厂仓库供货