

说明:
 - 带锻造的锉柄，毫无缺陷的钢结构
 - 均匀的锉纹和锉齿

应用:
 车间和工厂用优质锉刀



Hieb 1 grob Hieb 2 mittel Hieb 3 fein



- 400100 扁锉 锉纹 1 (粗)
- 400200 扁锉 锉纹 2 (中)
- 400300 扁锉 锉纹 2 (中)

| 锉纹长度 mm | 400100 (RG 4070) | 400200 (RG 4070) | 400300 (RG 4070) | 横截面 mm |
|------------|---------------------|---------------------|---------------------|-----------|
| 100 | ● | ● | ● | 12×2,5 |
| 150 | ● | ● | ● | 16×4 |
| 200 | ● | ● | ● | 20×5 |
| 250 | ● | ● | ● | 25×6 |
| 300 | ● | ● | ● | 30×6,5 |
| 350 | ● | ● | — | 35×7,5 |



- 401100 方锉 锉纹 1 (粗)
- 401200 方锉 锉纹 2 (中)
- 401300 方锉 锉纹 3 (细)

| 锉纹长度 mm | 401100 (RG 4070) | 401200 (RG 4070) | 401300 (RG 4070) | 横截面 mm |
|------------|---------------------|---------------------|---------------------|-----------|
| 100 | ● | ● | ● | 4 |
| 150 | ● | ● | ● | 6 |
| 200 | ● | ● | ● | 8 |
| 250 | ● | ● | ● | 10 |
| 300 | ● | ● | — | 12 |



- 402100 三角锉 锉纹1 (粗)
- 402200 三角锉 锉纹2 (中)
- 402300 三角锉 锉纹3 (细)

| 锉纹长度 mm | 402100 (RG 4070) | 402200 (RG 4070) | 402300 (RG 4070) | 横截面 mm |
|------------|---------------------|---------------------|---------------------|-----------|
| 100 | ● | ● | ● | 8,0 |
| 150 | ● | ● | ● | 11,0 |
| 200 | ● | ● | ● | 15,0 |
| 250 | ● | ● | ● | 17,5 |
| 300 | ● | ● | — | 20,0 |



- 403100 半圆锉 锉纹 1 (粗)
- 403200 半圆锉 锉纹 2 (中)
- 403300 半圆锉 锉纹 3 (细)

| 锉纹长度 mm | 403100 (RG 4070) | 403200 (RG 4070) | 403300 (RG 4070) | 横截面 mm |
|------------|---------------------|---------------------|---------------------|-----------|
| 150 | ● | ● | ● | 16×4,5 |
| 200 | ● | ● | ● | 20×6 |
| 250 | ● | ● | ● | 25×7 |
| 300 | ● | ● | ● | 30×8,5 |
| 350 | ● | — | — | 35×10 |

● = 德国中央仓库库存
 ○ = 德国工厂仓库供货